



GoldSeal™ refurbished coil exchange¹ saves you up to 60 percent.



Can you afford to wait for a coil repair?

Coil replacement can claim a big share of MR system ownership cost. Meanwhile, waiting for coil repairs can interrupt service to patients and erode your revenue stream. Now you can save up to 60 percent off of new coil list prices and avoid spending time waiting for someone to repair your coil through our GoldSeal refurbished coil exchange¹.

The program is simple

- 1 You notify us that a coil has failed.
- 2 We immediately ship a validated replacement from our inventory of refurbished coils.
- 3 Send us your old coil in exchange.

Every GoldSeal refurbished coil is extensively tested and validated to meet GE specifications.

GoldSeal refurbished coils¹ combine quality and value:

- More than three decades experience in MR imaging systems and coils
- Tested and validated to OEM medical device specifications using ISO 13485 quality system
- Available same-day or next-day shipping and a 120-day warranty
- Technical support through end of life as needed from dedicated installed base engineers

Act now to receive up to 60 percent off list price for a limited time.²

Call now **800-558-2040, option 1**
Or order online 24/7 at **ServiceShop.gehealthcare.com**

¹ This program does not cover every GE MRI coil. Check with a customer service representative for part availability.

² Discount applies to purchases completed on or before 12/31/17.

©2017 General Electric Company – All rights reserved.
GoldSeal is a trademark of the General Electric Company.